

UNIT NUMBER SWMU 100

UNIT NAME Fire Training Area

REGULATORY STATUS: AOC (CERCLA)

LOCATION: South of C-747 Oil Land Farm and at the west side of 4th street

APPROXIMATE DIMENSIONS: 20ft x 20ft

FUNCTION: Combustible liquids may have been burned in pits for fire training exercises, the area is still utilized for fire training with the combustible liquids contained in a metal pan

OPERATIONAL STATUS: In place

DATES OPERATED: 1982 - 1987

SITE/PROCESS DESCRIPTION: Waste oils, solvents, and other combustible liquids may have been burned at this location for fire training exercises

WASTE DESCRIPTION: possible TCE or PCB-contaminated waste oils and solvents

WASTE QUANTITY: unknown

DESCRIPTION OF RELEASE: Unburned materials may have been released to the ground. Refer to the Phase II report for additional details.

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES

This area underwent a prioritized RFI under the CERCLA ACO. Results of prioritized investigation did not indicate this unit to be a significant contribution to offsite contamination. This area will be addressed with WAG 1. The RFI plan for this WAG will be submitted in accordance with the schedule in the HSWA permit.



